

Final Reclamation Inspection

December 8th, 2023

Operator: Hilcorp Energy Company - 10133

Location ID: 333989

Inspection Document #: 714000210

La Plata County, CO

Township: NENE 32 34N 9W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Ballantine 34-9 32-4A
Location ID: 333989

12/8/23
+37.151443,-107.843484
179° S



Photo 1. View of the project area taken from the entrance facing center.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-09460

Inspection Photos

Location Name: Ballantine 34-9 32-4A

Location ID: 333989



Photo 2. View of failing stormwater erosion BMPs observed in the northern interim reclamation area adjacent to the access point/entrance. Additional stabilization is needed in this area.

API #:067-05515



Photo 3. View of weedy debris observed in the western interim reclamation area.

Inspection Photos

Location Name: Ballantine 34-9 32-4A

Location ID: 333989



Photo 4. View of soil piles stored on in the western and northern interim reclamation areas. This is considered debris and needs to be removed.