

Final Reclamation Inspection

December 8th, 2023

Operator: Simcoe LLC - 10749

Location ID: 334008

Inspection Document #: 714000211

La Plata County, CO

Township: NENE 33 34N 9W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Phillips A 4, A2
Location ID: 334008



Photo 1. View of the project area taken from the entrance facing center.



API #: 067-09610, 09611



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Phillips A 4, A2
Location ID: 334008



12/8/23
+37.152008,-107.823643
116° SE

Photo 2. View of the southern interim reclamation area facing southeast.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #:067-05515

Inspection Photos
Location Name: Phillips A 4, A2
Location ID: 334008



Photo 3. View of the eastern interim reclamation area facing northeast.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #:067-05515

Inspection Photos
Location Name: Phillips A 4, A2
Location ID: 334008



Photo 4. View of the reference area comprised of poa secunda and juniper.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #:067-05515