

Final Reclamation Inspection

December 8th, 2023

Operator: Simcoe LLC - 10749

Location ID: 306818

Inspection Document #: 714000212

La Plata County, CO

Township: SENW 34 34N 9W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Zellitti A 2
Location ID: 306818



Photo 1. View of the project area taken from the entrance facing center.



API #: 067-08834



Inspection Photos
Location Name: Zellitti A 2
Location ID: 306818



Photo 2. View of the eastern and southern interim reclamation areas.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #:067-05515

Inspection Photos
Location Name: Zellitti A 2
Location ID: 306818



Photo 3. View of stained soils near muffler on location.

Inspection Photos
Location Name: Zellitti A 2
Location ID: 306818



Photo 4. View of the reference area comprised of smooth brome.