

Final Reclamation Inspection

December 8th, 2023

Operator: Simcoe LLC - 10749

Location ID: 333564

Inspection Document #: 714000213

La Plata County, CO

Township: SWNE 34 34N 9W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Zellitti 1 A, A 3
Location ID: 333564

12/8/23
+37.149961,-107.809263
184° S



Photo 1. View of the project area taken from the entrance facing center.



Inspection Photos
Location Name: Zellitti 1 A, A 3
Location ID: 333564



Photo 2. View of stained soils observed on location.

Inspection Photos
Location Name: Zellitti 1 A, A 3
Location ID: 333564



Photo 3. View of gravel pile on location. This is considered debris and needs to be removed.

Inspection Photos
Location Name: Zellitti 1 A, A 3
Location ID: 333564



Photo 4. View of the eastern interim reclamation area facing south.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #:067-05515

Inspection Photos
Location Name: Zellitti 1 A, A 3
Location ID: 333564



Photo 5. View of the reference area comprised of rabbit brush and smooth brome.