

Final Reclamation Inspection

December 8th, 2023

Operator: Simcoe LLC - 10749

Location ID: 325691

Inspection Document #: 714000215

La Plata County, CO

Township: NWNW 35 34N 9W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Turner Securities A 1
Location ID: 325691



12/8/23
+37.154149,-107.801914
99° E



Photo 1. View of the project area taken from the entrance facing center.



Inspection Photos
Location Name: Turner Securities A 1
Location ID: 325691



Photo 2. View of rill erosion forming on the eastern edge of the disturbance. Additional erosion BMPs needed in this area.



Inspection Photos
Location Name: Turner Securities A 1
Location ID: 325691



Photo 3. Fence has been installed delineating active disturbance and surface owners storage area.

Inspection Photos
Location Name: Turner Securities A 1
Location ID: 325691



Photo 4. View of southern interim reclamation area facing south.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #:067-05515

Inspection Photos
Location Name: Turner Securities A 1
Location ID: 325691



Photo 5. View of the reference area comprised of smooth brome, rabbit brush and juniper.