

Final Reclamation Inspection

December 8th, 2023

Operator: Simcoe LLC - 10749

Location ID: 333470

Inspection Document #: 714000216

La Plata County, CO

Township: SWNE 35 34N 9W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Turner Securities A 4, A 2
Location ID: 333470



Photo 1. View of the project area taken from the entrance facing center.



Inspection Photos

Location Name: Turner Securities A 4, A 2

Location ID: 333470



Photo 2. View of rill/gully erosion forming in the western portion of the interim reclamation area. Additional erosion BMPs are needed for this area.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #:067-05515

Inspection Photos
Location Name: Turner Securities A 4, A 2
Location ID: 333470



Photo 3. View of debris/unused equipment observed on location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #:067-05515

Inspection Photos
Location Name: Turner Securities A 4, A 2
Location ID: 333470



Photo 4. Reference area comprised of juniper and poa secunda.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #:067-05515