

# Final Reclamation Inspection

December 8th, 2023

Operator: Simcoe LLC - 10749

Location ID: 333997

Inspection Document #: 714000218

La Plata County, CO

Township: SWNE 36 34N 9W M

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



Inspection Photos

Location Name: Federal Land Bank C 4, C 3

Location ID: 333997



**Photo 2.** View of rill/gully erosion forming in the eastern interim reclamation area.



Inspection Photos

Location Name: Federal Land Bank C 4, C 3

Location ID: 333997



**Photo 3.** View of failing storm water BMPs and additional rill erosion forming in the eastern interim reclamation area.

Inspection Photos  
Location Name: Federal Land Bank C 4, C 3  
Location ID: 333997



**Photo 4.** Pile of gravel observed on location, this is considered debris and needs to be removed.



Inspection Photos  
Location Name: Federal Land Bank C 4, C 3  
Location ID: 333997



Photo 5.

