

Final Reclamation Inspection

December 8th, 2023

Operator: Simcoe LLC - 10749

Location ID: 334003

Inspection Document #: 714000220

La Plata County, CO

Township: SESW 30 34N 9W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Southern Ute DD 2
Location ID: 334003



12/8/23
+37.156472,-107.762045
338° N

Photo 1. View of the disturbance from the entrance facing center.



12/8/23
+37.156682,-107.762313
2° N



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-09694

Inspection Photos
Location Name: Southern Ute DD 2
Location ID: 334003



Photo 2. View of the eastern interim reclamation area facing north.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #:067-05515

Inspection Photos
Location Name: Southern Ute DD 2
Location ID: 334003



Photo 3. View of the interim western reclamation area facing south.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #:067-05515

Inspection Photos
Location Name: Southern Ute DD 2
Location ID: 334003



12/8/23
+37.157299,-107.761770
4° N

Photo 4. Reference area comprised of rabbit brush and smooth brome.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #:067-05515