

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/8NESE

Location ID: 323803

Date: 12/11/2023



NE End of Location – Photo #08035



Wellhead – Photo #08036

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/8NESE

Location ID: 323803

Date: 12/11/2023



Separator – Photo #08037



Tank Battery – Photo #08038

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/8NESE

Location ID: 323803

Date: 12/11/2023



Lack of Stabilization – Photo #08040



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #08041