

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Location Name: State Antelope 11-13HZ

Loc ID: 422603

Inspection: 696305483



Exhibit A

CA: Unused Wellhead Parts at Pumping Unit; see photos. Comply with Rule 606.

CA Resolution: Operator has reported that identified wellhead parts at the pumping unit have been properly removed to comply with Rule 606.