

Inspection Photos
Location Name: George H. Gerhardt 4
Location ID: 326734



Photo 1 Location.



Photo 2 WH sign.

Inspection Photos
Location Name: George H. Gerhardt 4
Location ID: 326734



Photo 3 WH.



Photo 4 Unused Pump jack disassembled in the field around the Well.

Inspection Photos
Location Name: George H. Gerhardt 4
Location ID: 326734



Photo 5 Unused Pump jack disassembled in the field around the Well.



Photo 6 Unused Pump jack disassembled in the field around the Well.