

Inspection Photos
Location Name: BRADBURYB#1
Location ID: 319895



Photo#1 Battery Sign/CA:Debris



Photo#2 Production Tank/Produced Water Tank/CA:Debris

Inspection Photos
Location Name: BRADBURYB#1
Location ID: 319895




Photo#3 CA:Debris



Photo#4 Separator/CA:Debris

Inspection Photos
Location Name: BRADBURYB#1
Location ID: 319895



Photo#5 Wellhead