

Inspection Photos
Location Name: Crow Valley 7-62-31-2H PAD
Location ID: 428129



Photo 1 – Current Operator no Present on Sign



Photo 2 – 7-62-30 2H Wellhead

Inspection Photos
Location Name: Crow Valley 7-62-31-2H PAD
Location ID: 428129



Photo 3 – Current Operator no Present on Sign



Photo 4 – 7-62-31 2H Wellhead



Inspection Photos
Location Name: Crow Valley 7-62-31-2H PAD
Location ID: 428129



Photo 5 – Tank Battery



Photo 6 – Tank Battery Sign

Inspection Photos
Location Name: Crow Valley 7-62-31-2H PAD
Location ID: 428129



Photo 7 – Water Tank Labels – Content, Capacity, NFPA



Photo 8 – Water Tank Labels – Content, Capacity, NFPA



Inspection Photos
Location Name: Crow Valley 7-62-31-2H PAD
Location ID: 428129



Photo 9 – Back side of Tank Battery



Photo 10 – Heater Treaters

Inspection Photos
Location Name: Crow Valley 7-62-31-2H PAD
Location ID: 428129



Photo 11 – Gas Meter House



Photo 12 – ECD

Inspection Photos
Location Name: Crow Valley 7-62-31-2H PAD
Location ID: 428129




Photo 13 – Risers not marked with OOSLAT



Photo 14 – Riser not marked with OOSLAT