

# Inspection Photos

12/11/2023

**Operator:** TEP ROCKY MOUNTAIN LLC - 96850

**Location ID:** 335438

**Inspection Doc:** 696205465

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335438



**Photo 1:** Photos provide an overview of the well-pad portion of the Location, facing southeast and southwest.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335438



**Photo 2:** Photos provide an overview of the battery portion of the Location, facing west and northwest.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335438



**Photo 3:** Photos examples showing visible vegetation over the interim areas of the Location. Observable vegetation was predominantly desirable perennial species, and appears uniform in establishment.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335438



**Photo 4:** Photo taken from the west end of the battery site. Photo shows ECD on the Location is disconnected and not in use. Unused equipment requires removal.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources