

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Location Name: ANTELOPE C-33

Loc ID: 466974

Inspection: 713900099



Exhibit A




Exhibit B

CA: Weed debris in the form of tumbleweeds were observed in each perimeter fence corner and in other areas around the location. Tumbleweeds are a troublesome annual nonnative weed that easily breaks off at the stem. Operator failed to control and manage weeds to prevent weed waste and prevent the spread of seeds onto adjacent lands. Comply with Rule 606 to remove weed debris.

CA Resolution: Operator has addressed and cleared weed debris and mowed location to comply with Rule 606.

CA: Interim reclamation activities have been performed to reduce disturbance areas only needed for production operations. Vegetation throughout the interim areas was mowed and had accumulation of tumbleweeds across the location so it has not met Rule 1003 standards.

CA Resolution: Operator has reported that identified areas have been crimped to help prevent regrowth of undesirable vegetation and bare areas have been reseeded.