

Inspection Photos
Location Name: Crow Valley 7-62-32 1M
Location ID: 422253



Energy and Carbon Management Commission
40.52678, -104.34525, 4857.4ft
12/11/2023 15:10:09



Energy and Carbon Management Commission
40.52681, -104.34522, 4862.1ft
12/11/2023 15:10:15

Photo 1 – Wellhead

Photo 2 – Wellhead Sign

Inspection Photos
Location Name: Crow Valley 7-62-32 1M
Location ID: 422253



Photo 3 – Tumbleweed Debris



Photo 4 – Unused Pipe