

**Inspection Photos**  
**Location Name: Pappenheim 6-62-26-0108BH**  
**Location ID: 432385**



**Photo 1 – Tank Battery**



**Photo 2 – Tank Battery Signs**

**Inspection Photos**  
**Location Name: Pappenheim 6-62-26-0108BH**  
**Location ID: 432385**



**Photo 3 – Tank Labels missing**



**Photo 4 – Tank Labels missing**

**Inspection Photos**  
**Location Name: Pappenheim 6-62-26-0108BH**  
**Location ID: 432385**




**Photo 5 – 3" Riser at Tank not OOSLAT**



**Photo 6 – Separator**

**Inspection Photos**  
**Location Name: Pappenheim 6-62-26-0108BH**  
**Location ID: 432385**



**Photo 7 – Risers at Separator**



**Photo 8 – Glycol Unit**

**Inspection Photos**  
**Location Name: Pappenheim 6-62-26-0108BH**  
**Location ID: 432385**




**Photo 9 – 1" Riser not OOSLAT**



**Photo 10 – Pumping Unit**

**Inspection Photos**  
**Location Name: Pappenheim 6-62-26-0108BH**  
**Location ID: 432385**



**Photo 11 – 1" Risers not OOSLAT**



**Photo 12 – Pipe Rack at Pumping Unit**