

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON-66S96W/8SENE

Location ID: 324199

Date: 12/11/2023



Location Entrance – Photo #08045



Wellhead – Photo #08047

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON-66S96W/8SENE

Location ID: 324199

Date: 12/11/2023



Separators – Photo #08048



Tank Battery – Photo #08051

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON-66S96W/8SENE

Location ID: 324199

Date: 12/11/2023



Unsecured Separator – Photo #08049



Unsecured Separator – Photo #08050

