

# Inspection Photos

12/11/2023

**Operator:** TEP ROCKY MOUNTAIN LLC - 96850

**Location ID:** 420224

**Inspection Doc:** 696205469

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 420224



**Photo 1:** Photo taken from the access road entrance, facing north. Signage not posted at location entrance.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 420224



**Photo 1:** Photos taken from the east end of the Location. Photos provide an overview from west to northwest.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 420224



**Photo 3:** Tank battery facility on the east end of the Location. Tank facility on the west end of the Location has been removed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 420224



**Photo 4:** Photos 4-5 taken from the slopes on the north and west end of the Location. Photos show operator has implemented/maintained hydromulch at the slopes.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 420224



**Photo 5:** Photos examples showing visible vegetation over the interim areas of the Location. Observable vegetation was predominantly desirable perennial species, and appears uniform in establishment.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 420224



**Photo 6:** Trash debris observed along fence of the wells.