

Inspection Photos
Location Name: Antelope K-15 PAD
Location ID: 435681



Energy and Carbon Management Commission
40.40724, -104.30973, 4591.4ft
12/12/2023 12:54:11

Photo 1 – Signs at Entrance



Energy and Carbon Management Commission
40.40619, -104.30899, 4642.7ft
12/12/2023 12:54:54

Photo 2 – Wellheads

Inspection Photos
Location Name: Antelope K-15 PAD
Location ID: 435681



Photo 3 – Chemical Containers missing Labels



Photo 4 – Chemical Containers missing Labels

Inspection Photos
Location Name: Antelope K-15 PAD
Location ID: 435681



Photo 5 – Gas Lift Injection Meter House