

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Location Name: State Antelope J-1 Pad

Loc ID: 440840

Inspection: 696305477



Exhibit A

CA: Risers at Tanks are Disconnected flowline risers not OOSLAT. See photos Complete flowline and crude oil transfer line abandonments to comply with Rule 1105.

CA Resolution: Operator has appropriately marked risers with tags noting "future use" to comply with Rule 1105.



Exhibit A

CA: Locate Tags on Location no longer in use or valid. See photos Comply with Rule 606

CA Resolution: Operator has removed from the location to comply with Rule 606.



Exhibit A

CA: Unused Chemical Container inside Tank Berm. See photos Comply with Rule 606

CA Resolution: Operator has appropriately removed unused equipment from the location to comply with Rule 606.

