

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, S. Parachute Federal/PF-31

Location ID: 334085

Date: 12/12/2023



Dec 12, 2023 at 09:16:59  
Parachute CO 81635  
United States

Location Entrance – Photo #08128



Dec 12, 2023 at 09:18:00  
Parachute CO 81635  
United States

Wellheads – Photo #08129

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, S. Parachute Federal/PF-31

Location ID: 334085

Date: 12/12/2023



Dec 12, 2023 at 09:19:36  
Parachute CO 81635  
United States

Separators – Photo #08131



Dec 12, 2023 at 09:20:36  
Parachute CO 81635  
United States

Tank Battery – Photo #08133



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, S. Parachute Federal/PF-31

Location ID: 334085

Date: 12/12/2023



Storage of Equipment/Supplies – Photo #08135

