

Inspection Photos

Location Name: FRANCIS-66N64W/8SENW

Location ID: 305115




Photo #1

Francis 22-8 (123-22515) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 160 yds.



Photo #2

Francis 22-8 Battery site

Abandoned: ALL Equipment Removed



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources