

Inspection Photos
Location Name: CAERUS PICEANCE LLC PD21 Pad
Location #: 334732



Photo # 9693 From entrance to location



Photo # 9694 From entrance to location

Inspection Photos
Location Name: CAERUS PICEANCE LLC PD21 Pad
Location #: 334732




Photo # 9695 Location

Photo # 9696 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC PD21 Pad

Location #: 334732



Photo # 9697 Location



Photo # 9698 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC PD21 Pad

Location #: 334732



Photo # 9699 Location

Photo # 9700 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC PD21 Pad
Location #: 334732



Photo # 9701 Location



Photo # 9702 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC PD21 Pad
Location #: 334732



Photo # 9703 Hole in liner/liner needs maintenance (single tank containment)



Photo # 9704 Hole in liner/liner needs maintenance (single tank containment)

Inspection Photos
Location Name: CAERUS PICEANCE LLC PD21 Pad
Location #: 334732



Photo # 9705 Hole in liner/liner needs maintenance (3 tank containment)



Photo # 9706 Hole in liner/liner needs maintenance (3 tank containment)

Inspection Photos

Location Name: CAERUS PICEANCE LLC PD21 Pad

Location #: 334732



Photo # 9707 Holes in liner/liner needs maintenance (single tank containment)



Photo # 9708 Hole in liner/liner needs maintenance (single tank containment)

Inspection Photos

Location Name: CAERUS PICEANCE LLC PD21 Pad

Location #: 334732



Photo # 9709 Hole in liner/liner needs maintenance (single tank containment)