

Inspection Photos
Location Name: Antelope 41-17 PAD
Location ID: 423795



Energy and Carbon Management Commission
40.40516, -104.34011, 4663.6ft
12/12/2023 13:30:01

Photo 1 – Wellheads



Energy and Carbon Management Commission
40.40508, -104.3402, 4637.5ft
12/12/2023 13:30:30

Photo 2 – Separators

Inspection Photos
Location Name: Antelope 41-17 PAD
Location ID: 423795



Energy and Carbon Management Commission
40.40525, -104.34014, 4636.8ft
12/12/2023 13:30:48

Photo 3 – Tank Battery



Energy and Carbon Management Commission
40.40626, -104.34004, 4622.2ft
12/12/2023 13:31:36

Photo 4 – Signs at Entrance