

**Inspection Photos**  
**Location Name: Antelope P-17 PAD**  
**Location ID: 428964**



**Photo 1 – Signs at Entrance**



**Photo 2 – Compressor – Day Tank Netting has been repaired**

**Inspection Photos**  
**Location Name: Antelope P-17 PAD**  
**Location ID: 428964**



**Photo 3 – Tank Battery**



**Photo 4 – Wellheads**



**Inspection Photos**  
**Location Name: Antelope P-17 PAD**  
**Location ID: 428964**



Energy and Carbon Management Commission  
40.40551, -104.34265, 4644.6ft  
12/12/2023 13:37:21

**Photo 5 – P-T-17HZ Wellhead**



Energy and Carbon Management Commission  
40.40533, -104.3429, 4631.6ft  
12/12/2023 13:38:07

**Photo 6 – Tank Battery**

**Inspection Photos**  
**Location Name: Antelope P-17 PAD**  
**Location ID: 428964**



**Photo 7 – Tank Battery Signs**



**Photo 8 – Separators and ECDs**

**Inspection Photos**  
**Location Name: Antelope P-17 PAD**  
**Location ID: 428964**



**Photo 9 – Gas Meter House**