

Inspection Photos

API: 099-06045

Operator: RENEGADE OIL & GAS COMPANY LLC

Inspection Date: 12/15/2023

County: Prowers



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast toward the tank battery. There is a new tank being installed which will need to follow the 603.k.o. requirements.



Inspection Photos



Photo 2. There is a new tank being installed which will need to follow the 603.k.o. requirements.



Inspection Photos



Photo 3. Facing west at the location. The fence and shed at the separator was removed.



Inspection Photos



12.15.2023

Photo 4. Facing southwest at the location. Unused areas of the location need to be reclaimed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API: 099-06045 | Date: 12/15/2023

Inspection Photos



Photo 5. Facing south at the east side of the location. Unused areas of the location need to be reclaimed.

