

Inspection Photos
Location Name: HSR-Miller Federal 15-6A
Location ID: 330898



Photo 1 WH sign over run with dead vegetation.



Photo 2 WH over run with dead vegetation.



Inspection Photos
Location Name: HSR-Miller Federal 15-6A
Location ID: 330898



Photo 3 Location over run with dead vegetation.



Photo 4 Wellsite over run with dead vegetation.