

**Inspection Photos**  
**Location Name: Dunham #41-5**  
**Location ID: 331146**



**Photo 1 Gate on access road to well overgrown vegetation**

**Photo 2 Overgrown vegetation on access road to well site**

Inspection Photos  
Location Name: Dunham #41-5  
Location ID: 331146



Photo 3 LOTO well head

Photo 4 loc pic

Inspection Photos  
Location Name: Dunham #41-5  
Location ID: 331146



Photo 5 TNK BTRY

Photo 6 production equipment