

# Inspection Photos

API: 011-06126

Operator: STRACHAN EXPLORATION INC

Inspection Date: 12/15/2023

County: Bent



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing south toward the location. The sign posted at meter shed is faded and not legible.



## Inspection Photos



**Photo 2.** Facing toward the tank battery. There is insufficient secondary containment to contain a spill.

