

Inspection Photos
Location Name: Antelope 14-19 PAD
Location ID: 413458



Photo 1 – Wellheads




Photo 2 – Unmarked Risers at 14-19 Wellhead

Inspection Photos
Location Name: Antelope 14-19 PAD
Location ID: 413458



Photo 3 – Unmarked Risers at 14-19 Wellhead



Photo 4 – Riser on Eastside has been tagged

Inspection Photos
Location Name: Antelope 14-19 PAD
Location: 413458



Photo 5 – Gas Lift Injection Meter House



Photo 6 – Container missing Labels