

Inspection Photos
Location Name: McCoy 1
Location ID: 318173



Photo 1 Location Entrance/sign.



Photo 2 WH/BOP.

Inspection Photos
Location Name: McCoy 1
Location ID: 318173



Photo 3 Accumulator trailer, location.



Photo 4 Axis Energy Services Bulk truck.

Inspection Photos
Location Name: McCoy 1
Location ID: 318173



Photo 5 Axis Cement equipment.



Photo 6 Circulation/fresh water tanks.



Inspection Photos
Location Name: McCoy 1
Location ID: 318173



Photo 7 Rig Pump.



Photo 8 location.