

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Domestic Tap 34NENW

Location # 323790

Facility # 456910



Photo # 378 Domestic tap



Photo # 379 Domestic tap

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Domestic Tap 34NENW

Location # 323790

Facility # 456910



Photo # 380 Domestic tap



Photo # 381 Domestic tap

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Domestic Tap 34NENW

Location # 323790

Facility # 456910



Photo # 382 Domestic tap



Photo # 383 Domestic tap

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Domestic Tap 34NENW

Location # 323790

Facility # 456910



Photo # 384 PRV vent line lacks cap



Photo # 385 PRV vent line lacks cap