

Inspection Photos

Loc: 308518

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 12/19/2023

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east toward the location.



Inspection Photos



Photo 2. Well sign is posted at meter shed. Operator name is peeling off.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:308518 | Date: 12/19/2023

Inspection Photos



Photo 3. Facing east toward the fill slope.



Inspection Photos



Photo 4. There is stained soils by the wellhead that will need to be cleaned up.

