

Operator: CRESTONE PEAK RESOURCES

Location Name: State Massive 1H

Loc ID: 436514

Inspection: 709400634

☀ 0°N (T) ● 39°38'59"N, 104°37'28"W ±13ft ▲ 5854ft



North east
weed mitigation

State Massive 1H
19 Dec 2023

Exhibit A

☀ 0°N (T) ● 39°38'59"N, 104°37'27"W ±13ft ▲ 5858ft



North west
weed mitigation

State Massive 1H
19 Dec 2023

Exhibit B

☀ 0°N (T) ● 39°38'58"N, 104°37'23"W ±13ft ▲ 5856ft



East weed mitigation

State Massive 1H
19 Dec 2023

Exhibit C

☀ 0°N (T) 🌐 39°38'55"N, 104°37'25"W ±13ft ▲ 5858ft



Exhibit D

CA: Failure to control and manage weeds to prevent weed waste and prevent the spread of seeds onto adjacent lands. Comply with Rule 606.c.

CA Resolution: Weeds have been removed to comply with Rule 606.c.