

Inspection Photos
Location Name: Johnston ET AL 20-01
Location ID: 322884



Photo 1 Loc pic



Photo 2 TNK BTRY



Inspection Photos
Location Name: Johnston ET AL 20-01
Location ID: 322884



Photo 3 production equipment



**Photo 4 Unused equipment pump in disrepair and no motor,
Stained soil around unit.**

Inspection Photos
Location Name: Johnston ET AL 20-01
Location ID: 322884



Photo 5 Well head



Photo 6 Stained soil around well head

Inspection Photos
Location Name: Johnston ET AL 20-01
Location ID: 322884



Photo 7 Wrong sign on well head