

Operator: CRESTONE PEAK RESOURCES
Location Name: STATE MASSIVE 5-65 2-3
Loc ID: 465461
Inspection: 709400633

☀ 0°N (T) ● 39°38'51"N, 104°37'27"W ±13ft ▲ 5833ft



State Massive 5-65 2-3

Exhibit A

☉ 0°N (T) ☉ 39°38'53"N, 104°37'21"W ±13ft ▲ 5836ft



State Massive 5-65 2-3

Exhibit B

☉ 0°N (T) ● 39°38'52"N, 104°37'28"W ±19ft ▲ 5843ft



State Massive 5-65 2-3

Exhibit C

☀ 0°N (T) ● 39°38'54"N, 104°37'26"W ±337ft ▲ 5859ft



State Massive 5-65 2-3

Exhibit D

☀ 0°N (T) ● 39°38'54"N, 104°37'22"W ±19ft ▲ 5838ft



State Massive 5-65 2-3

Exhibit E

☼ 0°N (T) ● 39°38'49"N, 104°37'24"W ±13ft ▲ 5818ft



State Massive 5-65 2-3

Exhibit F

☉ 0°N (T) ● 39°38'49"N, 104°37'23"W ±13ft ▲ 5817ft



State Massive 5-65 2-3

Exhibit G



Exhibit H

☉ 0°N (T) ● 39°38'53"N, 104°37'28"W ±52ft ▲ 5847ft



Exhibit I

☼ 0°N (T) ● 39°38'49"N, 104°37'24"W ±16ft ▲ 5819ft



State Massive 5-65 2-3

Exhibit J

☉ 0°N (T) ☉ 39°38'52"N, 104°37'28"W ±52ft ▲ 5841ft



State Massive 5-65 2-3

Exhibit K

CA: Failure to control and manage weeds to prevent weed waste and prevent the spread of seeds onto adjacent lands. Comply with Rule 606.c

CA Resolution: Weeds have been removed to comply with Rule 606.c.

CA: Topsoil stockpile is inundated with weeds and bare areas. All stockpiled soils shall be protected from degradation due to contamination, compaction and, to the extent practicable, from wind and water erosion during drilling and production operations. Best management practices to prevent weed establishment and to maintain soil microbial activity shall be implemented. Comply with rule 1002.c

CA Resolution: Stockpiled soils have been protected, weeds have been managed and soil microbial activity has been implemented to comply with Rule 1002.c.

CA: Interim areas and topsoil stockpile are not progressing towards 1003 revegetation standards. Perform reclamation per Rule 1003. Establish vegetation with total perennial, non-invasive uniform plant cover of at least 80 percent of reference area levels. Use surface owner seed mixture, or one prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage the site. Vegetation in interim areas are predominantly undesirable species (Kochia, Russian thistle). Comply with Rule 1003.

CA Resolution: Location has had proper reclamation to comply with Rule 1003.