

Inspection Photos
Location Name: UPRR 42 Pan Am G 2
Location ID: 317758



Photo 1 Well sign.



Photo 2 Dead vegetation around the WH.

Inspection Photos
Location Name: UPRR 42 Pan Am G 2
Location ID: 317758



Photo 3 Ancillary equip.

Photo 4 Dead vegetation around the Pump jack.