

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S95W/31NENE

Location ID: 335491

Date: 12/18/2023



Location Entrance – Photo #08202



Wellheads – Photo #08203

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S95W/31NENE

Location ID: 335491

Date: 12/18/2023



Separators – Photo #08207



Tank Battery – Photo #08204

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S95W/31NENE

Location ID: 335491

Date: 12/18/2023



Debris – Photo #08205



Lack of Stabilization – Photo #08211

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S95W/31NENE

Location ID: 335491

Date: 12/18/2023



Lack of Stabilization – Photo #08212



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #08213**