

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S95W/31SENE

Location ID: 335414

Date: 12/18/2023



Location Entrance – Photo #08215



Location Entrance – Photo #08221



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S95W/31SENE

Location ID: 335414

Date: 12/18/2023



Wellheads – Photo #08222



Separators – Photo #08216



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S95W/31SENE

Location ID: 335414

Date: 12/18/2023



Tank Battery – Photo #08217



Stored Equipment – Photo #08219



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S95W/31SENE

Location ID: 335414

Date: 12/18/2023



Stored Equipment – Photo #08220



Lack of Stabilization – Photo #08223

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S95W/31SENE

Location ID: 335414

Date: 12/18/2023



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit**  
– Photo #08224