

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S95W/31NESE

Location ID: 324073

Date: 12/18/2023



Location Entrance – Photo #08226



Wellhead – Photo #08227

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S95W/31NESE

Location ID: 324073

Date: 12/18/2023



Separator – Photo #08229



Tank Battery – Photo #08228

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S95W/31NESE

Location ID: 324073

Date: 12/18/2023



Lack of Stabilization – Photo #08231



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #08232