

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PA/313-32

Location ID: 324195

Date: 12/18/2023



Wellhead – Photo #08235



Separators – Photo #08238



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PA/313-32

Location ID: 324195

Date: 12/18/2023



Dec 18, 2023 at 12:55:23  
Parachute CO 81635  
United States



Dec 18, 2023 at 12:51:51  
Parachute CO 81635  
United States

Tank Battery – Photo #08239

Lack of Stabilization – Photo #08236



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PA/313-32

Location ID: 324195

Date: 12/18/2023



Lack of Stabilization – Photo #08237



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit  
– Photo #08240