

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PA-66S95W/32SWSW

Location ID: 334918

Date: 12/18/2023



Wellheads – Photo #08242



Separators – Photo #08238

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PA-66S95W/32SWSW

Location ID: 334918

Date: 12/18/2023



Tank Battery – Photo #08239

Lack of Stabilization – Photo #08244

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PA-66S95W/32SWSW

Location ID: 334918

Date: 12/18/2023



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #08245**