

Work Completion Report

Contractor: Peerless

JOB DETAILS

Job Name	Month/Season	Completed By	Completion Date
SHARON 1-8HZ		Armando Munoz	12/19/2023
Work Summary	Reclamation Type	Land Use	
Repaired erosion on slopes and facility and well pad fixed access road. And well pad road	Stormwater	Active Pad	
One-Call Number	Red Zone Rep	Red Zone Date	

WORK TASK

Task Name	Priority	COGCC Compliance	Task Location and Notes/Instructions
Stormwater Repairs	High	No	Location(s): Sharon_4N67W21O Notes: Repair erosion which has formed throughout slopes of facility and associated lease road. Blade and/or skid likely needed to address. NO DIGGING.

COMPLETION DETAILS

Total Area Affected: **1.85 acres**
Seed Mix: **None used**
Crop Type: **Corn**
Soil Type: **Clay Loam**
Stabilization Date: **12/19/2023**
Seeding Date:
Mulch: **None**
Straw Bales: **NA**
Soil Amendment Type: **None**
Soil Amendment Rate: **NA**
Imported Top Soil: **NA**
Top Soil Source: **NA**
General Notes:

LOCATION INFO

Location(s) – Name: Sharon_ 4N67W210

COGCC ID: **448107**
Well APIs at Location: **12343760 12343761 12343762 12343763 12343764 12343765 12343766 12343767**
Land Rep:
Land Owner: **Ron Walters**
Rec Contractor PO(s): **Peerless: 4501724436**
Vendor PO(s):
Billing Notes: **DJ-L0980**
Legal Address: **(WELD) NESW 21 4N67W**
Topsoil Source:
Variance Notes:
Private Utility Notes:
Wildlife Restrictions:
General Notes:
COGCC Doc #'s:
Initial Reclaim Complete Date:
Maint. Reclaim Complete Date:

PHOTOS

Photo Name: Site Map

Description:

Description:



Photo Name: Pre-Completion

Description:




Photo Name: Post-Completion

Description:



Photo Name: Sharon 2

Description:



Photo Name: Sharon 3

Description:



Photo Name: Sharon 4

Description:



Photo Name: Sharon 5

Description:

