

Sam 25H-M166

Location ID 453474


Spill ID 484966

Field Assessment & Sampling Activities

September-December 2023



Initial Assessment – 09/08/23




Looking east-southeast at initial excavation

Petroleum hydrocarbon staining and odor observed


Hand auger utilized within and adjacent to excavation to attempt preliminary delineation – hand auger limited by lithology

Delineation Activities – 10/26/23



Looking north
Hydrovac/hand auger utilized to delineate release

No petroleum hydrocarbon staining and odor observed



Looking east
Hydrovac/hand auger utilized to delineate release

No petroleum hydrocarbon staining and odor observed

Delineation Activities – 10/26/23



Looking south
Hydrovac/hand auger utilized to delineate release

Slight petroleum odor observed



Looking west
Hydrovac/hand auger utilized to delineate release


No petroleum hydrocarbon staining and odor observed

Delineation Activities – 10/26/23



Looking north
Hydrovac/hand auger utilized to delineate release


No petroleum hydrocarbon staining and odor observed



Looking north
Hydrovac/hand auger utilized to delineate release


No petroleum hydrocarbon staining and odor observed

Delineation Activities – 10/26/23



Looking north
Hydrovac/hand auger utilized to delineate release


No petroleum hydrocarbon staining and odor observed



Looking north
Hydrovac/hand auger utilized to delineate release


No petroleum hydrocarbon staining and odor observed

Facility Change Assessment – 11/16/23



Looking south
Grab samples collected adjacent to planned line removals

No petroleum hydrocarbon staining or odor observed



Looking south
Grab samples collected adjacent to planned line removals

No petroleum hydrocarbon staining or odor observed


Facility Change Assessment – 11/16/23



TB-SS-05
PID = 17.6 ppm

Looking south
Grab samples collected adjacent to planned line removals

Slight petroleum hydrocarbon odor observed



TB-SS-06
PID = 21.4 ppm

Looking east
Grab samples collected adjacent to planned line removals

Slight petroleum hydrocarbon odor observed