

Inspection Photos
Location Name: HSR Stroh 11-35
Location ID: 326834




Energy & Carbon Management Commission
40.35607, -104.86118, 1472.5m, 138°
12/21/2023 10:11:02

Production facility



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: HSR Stroh 11-35
Location ID: 326834



Emergency contact number on 11/2/2023



Emergency contact number on 12/21/2023

Inspection Photos
Location Name: HSR Stroh 11-35
Location ID: 326834



Manifold leaks on 11/2/2023



Manifold leaks on 12/21/2023