

**Inspection Photos**  
**Jilison 2A**  
**Spill ID 481527/Remediation Project No 23092**



**Photo 1 – Site photo.**



**Photo 2 - Open excavation.**



**Inspection Photos**  
**Jilison 2A**  
**Spill ID 481527/Remediation Project No 23092**



**Photo 3 – Weeds/Monitoring Well**



**Photo 4 - Former soil stockpile location.**



**Inspection Photos**  
**Jilison 2A**  
**Spill ID 481527/Remediation Project No 23092**



**Photo 5 – Former soil stockpile location.**



**Photo 6 - Former soil stockpile location.**



**Inspection Photos**  
**Jilison 2A**  
**Spill ID 481527/Remediation Project No 23092**



**Photo 7 – Weeds/fencing.**



**Photo 8 - Weeds/fencing.**



**Inspection Photos**  
**Jilison 2A**  
**Spill ID 481527/Remediation Project No 23092**



**Photo 9 – Weeds/fencing.**



**Photo 10 - Weeds/fencing.**



**Inspection Photos**  
**Jilison 2A**  
**Spill ID 481527/Remediation Project No 23092**



**Photo 11 – Weeds/fencing.**



**Photo 12 - Weeds/fencing.**



**Inspection Photos**  
**Jilison 2A**  
**Spill ID 481527/Remediation Project No 23092**



**Photo 13 – Weeds/fencing.**



**Photo 14 - Open excavation with salt crust.**



**Inspection Photos**  
**Jilison 2A**  
**Spill ID 481527/Remediation Project No 23092**



**Photo 15 – Trash in excavation.**



**Photo 16 - Open excavation.**