

Inspection Photos

Loc: 417026

Operator: **INCREMENTAL OIL & GAS (FLORENCE) LLC**

Inspection Date: 12/21/2023

County: FREMONT



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast toward the wellsite location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:417026 | Date: 12/21/2023

Inspection Photos



Photo 2. Facing toward onsite tank battery.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:417026 | Date: 12/21/2023

Inspection Photos



Photo 3. Facing toward the well. There is stained soils at the wellhead that need to be cleaned up.



Inspection Photos



Photo 4. Facing north at the location. The area north of the well site needs to be reseeded.



Inspection Photos



Photo 5. Facing west at the location. The area north of the well site needs to be reseeded.



Inspection Photos



Photo 6. Facing southwest at the location. The area north of the well site needs to be reseeded.

