

**Operator: EXTRACTION OIL & GAS INC**

**Location Name: Hergert 35-L Pad**

**Loc ID: 453075**

**Inspection: 697008354**



**Exhibit A**

**CA:** #7 methanol system lacks placards, see attached photo. Install sign to comply with Rule 605.h.

**CA Resolution:** Operator has appropriately updated and installed placards on the #7 methanol system to comply with Rule 605.h.