

Inspection Photos

Loc: 307312

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 12/26/2023

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing north at the access road.



Inspection Photos



Photo 2. Facing north at the west side of the location.



Inspection Photos



Photo 3. Facing north at the east side of the location.



Inspection Photos



Photo 4. Facing north at the south side of the location.



Inspection Photos



Photo 5. Facing south toward the offsite pit that is no longer in use. The area of the pit was pre-existing prior to the wellsite.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:307312 | Date: 12/26/2023

Inspection Photos



Photo 6. Facing north toward the embankment of the pre-existing offsite pit.



Inspection Photos



Photo 7. There is erosion along this area where water is discharged in storm events. This area should be armored and stabilized.



Inspection Photos



Photo 8. The embankment of the pre-existing pit is not stabilized and should be vegetated for long-term stabilization.

